



Replacement Sheet

2/6




FIG. 2



Replacement Sheet

5/6

TRANSFORMATION TEMPERATURE EFFECT ON FATIGUE OF 4 mil Ti21S AT 35 ksi, R 0.1




FIG. 5